

DATE	July 28, 2017
PRODUCT(S) AFFECTED	Perfecta® 3600STP w/VariQuest Design Center Software 6.0
SERIAL NUMBER(S)	All

TITLE:

Perfecta 3600STP: Printing Certificates using VariQuest Design Center Software 6.0.

DESCRIPTION OF ISSUE:

When creating certificates using the **search by keyword** function to find a template, the print will not size the output properly. This is only when printing to the Perfecta 3600STP printer with VQ Software 6.0



RESOLUTION:

Use **Browse Category**, select **Recognition and Motivation** then **Certificate** templates.

